

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N. R. 26 + 27 W. S. Mer. 5

44 Sec. Corner common to Sections
25, and 30

Corner consists of a 7th corner (not) in place
State condition _____

Dimensions above ground _____ inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ located _____

Pits are located _____

Sketch markings of Bearing (Trees or Rocks) in proper box and fill blanks below, giving bearing from Corner to Trees and Distances in Links.

<u>145</u>
<u>25</u>

<u>TOP</u>

<u>fully</u>
<u>stump</u>

<u>left</u>

<u>B.T.</u>

<u>B.T.</u>

--

--

Species R. Oak R. Oak _____

Diameter 8" 6" _____

Bearing N 27° 5' N 150° E _____

Distance 317ks. 25ks. _____

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? _____

Signature.


F. Ranger
Title.

12-11-30

Date.

Corner again
first with road &
falling distance from
Farm Y to Co. road D
Chase to Indian house

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near corner.)

8-2021

T. 146 N. R. 26-27W S. Mer.