

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

J-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 26 W 5th Mer.

1/4 Corner common to Sections

18 and 7

Corner consists of a Nothing (not) in place



State condition Gone

Dimensions above ground None inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT

BT

Species N. Pine J. Pine

Diameter 23 12

Bearing S.W N.E

Distance

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Edward Innesen

Signature.

9-16-29

Estimator

Date.


Title.

J-3

(Make sketch of topography near corner.)

V-3

T. 145 N. R. 26 W. S. 24 Mer.



Metal Location Poster is on a Jack Pine

tree 18 inches diameter, on the N.E.

side of corner

from which this Corner bears S.W.

about 3 chains distant.

Give any further facts which will aid in finding this

Corner again.