

U. S. Department of Agriculture

FOREST SERVICE

P 5
E-9 136

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 26W 5th Mer.

Section Corner common to Sections

4, 5, 8, and 9

Corner consists of a Cedar Post (~~stone~~) in place


State condition Good

Dimensions above ground 72 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspic

Diameter 6"

Bearing S 89° W

LKs Distance 14

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

J A Gjelhaug
(Signature)

9/18/35
(Date)

Jr. Civil Engr.
(Title)

Found old post. Set new cedar post in its place. Old BTs gone. Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears N 89° E

side of Tree

tree 6" inches diameter, on the East

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 149N R. 26W S. 74 Mer.