

U. S. Department of Agriculture  
FOREST SERVICE

*Posted*  
*e-9*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 26 5<sup>th</sup> Mer.  
YA Corner common to Sections

1, and 5

Corner consists of a Post (not) in place

State condition: Sound

Dimensions above ground 4' high; 3" dia inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species Sproce Spruce

Diameter 6" 7"

Bearing S15°E N78°W

Distance 17' 35'

Do you believe this to be a genuine Land Office Corner? Yes

~~If not, why?~~ Corner and bearing trees

are scribed but the figures are

illegible and indistinct.

*H. M. K. ...*  
(Signature)

7/12/34  
(Date)


F. ...  
(Title) F-27

Corner again.  
 Follow Inger Fireway #1 to point of crossing of section line. Station has marker and post set in place. Then follow cleared line (pickets in place) to corner

Give any further facts which will aid in finding this chains distant.

18. from which this Corner bears W 30 S

side of the tree.  
 tree 6" inches diameter, on the West  
 Metal Location Poster is on a Bl. Spruce



(Make sketch of topography near Corner)

Form 574-9—Revised May, 1913  
U. S. Department of Agriculture  
FOREST SERVICE

C-9

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 146 R. 26 5th Mer.

1/4 section Corner common to Sections

....., 5, and 4

Corner consists of a wood post (not) in place


State condition good

Dimensions above ground 3" x 3" x 36" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E





NW SW SE NE

Mound of ..... is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tom. st. b. Tom. st. b.

Diameter 4" 4"

Bearing N77°W S10°E

Distance .41 .28

Do you believe this to be a genuine Land Office Corner? yes

If not, why? .....

Walter Kahrh

(Signature)

11/9/38  
(Date)

Leader  
(Title)

WATER RESOURCES DIVISION

FIELD NOTES

CONCORD, MASSACHUSETTS

SECTION 6, T. 14 N., R. 26 E., S. 47

Corner again. **Spruce 6" S. 33° E. 17.45 = 0.7.**

Give any further facts which will aid in finding this


**131 M** chains distant.

from which this corner bears **S 78° W**

side of **corner**

tree **4"** inches diameter, on the **WEST**

Metal Location Poster is on a **Spruce**



(Sketch sketch of topography near center)