

U. S. Department of Agriculture
FOREST SERVICE

Posted
A-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146⁺147 R. 26 5⁺6 P. Mer.

Section Corner common to Sections
4, 5, 32, and 33

Corner consists of a Tan Post (not) in place
State condition Worn from exposure - illegible

Dimensions above ground 2' high - 3" dia. inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


H. W. [Signature]
(Signature)

8/6/34
(Date)

Emmerson - F-27
(Title)

Corner again.
 Follow Inger Firway #1 to
 section line - indicated by
 section line marker white
 post. Follow cleared picket
 line E. to corner

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears $5.87^{\circ} W$
 side of
 tree $5''$ inches diameter, on the
 Metal Location Poster is on a *Tamarack*



(Make sketch of topography near Corner)