

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

E-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ¹⁴⁶ W R. ²⁷ N ²⁶ S P Mer.

Section

Corner common to Sections

Land 12 146-27

and 6-17 in 146-26

Corner consists of a #3 1/2" stake 5" x 5" (set) in place

State condition Good Upright

Dimensions above ground 3 1/2" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

T 146W R27 S1	T 146 R27 S 12	T 146 R26 S7	T 146 R26 S6
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 146 R27 S1 <i>Has a place N.E. from it.</i>			

Species Aspen

Diameter 13"

Bearing N20W

Distance 22'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Robby and Horton
Signature.

Nov. 8, 1928.
Date.

Forest Rangers
Title. E-1 3027

