

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

P
 R-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N. R. 27 W. 5th P. Mer.

Section Corner common to Sections
20, 21, 28, and 29

Corner consists of a Oak Post (~~not~~) in place



State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Pine N. Pine J. Pine

Diameter 16" 20" 10"

Bearing N. 23 W. S. 23 W. S. 65 W.

Distance 58 88 21

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


J. A. Golthaus
 (Signature)

4/29/37
 (Date)

Jr. Civil Eng
 (Title)

SECTION 29
 SECTION 28
 SECTION 27
 SECTION 26

Corner again:
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears *N 65° E*
 side of *tree*
 tree *10* inches diameter, on the *N E*
 Metal Location Poster is on a *Pin*



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

R-9 R

Chippewa NATIONAL FOREST


CORNERS OF THE PUBLIC SURVEY

T. 146N R. 27W 5th P. Mer.

Section Corner common to Sections
 20, 21, 28, and 29

Corner consists of a Oak Post (not) in place
 State condition Good


Dimensions above ground 48 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Pine A. Pine 5/8" J.P.
 Diameter 16" rotten 20" 10"
 Bearing N 23° W S 23° W S 65° W
 Distance 58 88 21


Do you believe this to be a genuine Land Office Corner? Yes
 If not, why? _____

4/29/37
 (Date)

J. A. Gjelhaug
 (Signature)
Jr. Civil Eng.
 (Title)

CORNER OF THE PUBLIC SURVEY
 GIVE ANY FURTHER FACTS WHICH WILL AID IN FINDING THIS
 CORNER AGAIN.

Metal Location Poster is on a *Back Pine*
 tree 10 inches diameter, on the *N.E.*
 side of *Tree*
 from which this Corner bears
0.271 chains distant.



(Make sketch of topography near Corner)

T. 186N. R. 27W. S. 2 P. Mer.