

V-1

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 & 30 5th Mer.
Section

Corner common to Sections 25, 36, 30, and 31

Corner consists of a metal cap (not) in place
State condition surrounded by cement

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

25		31	30
----	--	----	----

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S .30			
-------	--	--	--

B.T.			
------	--	--	--

Species J. Pine

Diameter 5"

Bearing N 36E

Distance 1.64 ch

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Harold Hennes

Jan. 11, 1937


(Signature)

(Date)

(Title)

V-1

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant
 Give any further facts which will aid in finding this
 Other signs
 (Name of land or owner)
 (Date)
 (Township)
 (Range)
 (Section)
 (County)
 (State)



(Make sketch of topography near Corner)

T. 100 N. R. 30 E. 30 W. Sec. 35
 Mer.