

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 27N 5th Mer.

C 1/4

Corner common to Sections

19

and

Corner consists of a Steel pipe (not) in place

State condition good brass cap

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|----|----|----|----|
| 19 | 19 | 19 | 19 |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | |
|------|--|
| C.S. | |
| S 19 | |

| | |
|--|--|
| | |
| | |

| | |
|------|--|
| C.T. | |
| S.19 | |

| | |
|--|--|
| | |
| | |

| | |
|------|--|
| B.T. | |
|------|--|

| | |
|--|--|
| | |
|--|--|

| | |
|------|--|
| B.T. | |
|------|--|

| | |
|--|--|
| | |
|--|--|

Species W. Oak W. Birch

Diameter 14" 25"

Bearing N35E S41W

Distance 22 lks 29 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No

Gene Tinderholm

(Signature)


March 25, 1937

(Date)

(Title)

COMPARISON OF THE
 CORNER BEARS

Metal Location Poster is on a White Oak Tree
 tree $1\frac{1}{2}$ inches diameter, on the R. Side
 side of $\frac{7}{8}$ 11th
 from which this Corner bears N 83 E
 32 1/2 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 29W 5th Mer.
C 1/4 Corner common to Sections

19, , and

Corner consists of a Steel pipe (not) in place
State condition good brass cap

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|----|----|----|----|
| 19 | 19 | 19 | 19 |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | |
|-------------------|--|
| C $\frac{1}{4}$ S | |
| S 19 | |

| | |
|--|--|
| | |
| | |

| | |
|-----------------|--|
| C $\frac{1}{4}$ | |
| S. 19 | |

| | |
|--|--|
| | |
| | |

| | |
|------|--|
| B.T. | |
|------|--|

| | |
|--|--|
| | |
|--|--|

| | |
|------|--|
| B.T. | |
|------|--|

| | |
|--|--|
| | |
|--|--|

Species W. Oak W. Birch

Diameter 14" 15"

Bearing N83E S41W

Distance 32 lks 29 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Gene Tinderholm
(Signature)


March 25, 1937

(Date)

(Title)

Corner again.

Metal Location Poster is on a White Oak tree
tree 1 1/2 inches diameter, on the E. Side
side of $\frac{1}{2}$ 11m
from which this Corner bears N 83 E
Give any further facts which will aid in finding this
Corner again.



(Place sketch of topography near Corner)