

**U. S. Department of Agriculture**  
**FOREST SERVICE**

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 146N R. 29W 5th Mer.

1/4 Corner common to Sections  
21, and 22

Corner consists of a Brass capped pipe (not) in place

State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u> <u>5215.22</u>			
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>T. 146N</u> <u>R. 29W</u> <u>1/4</u> <u>5.22</u>	<u>T. 146N</u> <u>R. 29W</u> <u>1/4</u> <u>5.21</u>		
<u>B.T.</u>	<u>B.T.</u>		

Species Aspen Birch

Diameter 10 in 6 in

Bearing S. 50° E S. 47° W

Distance 24 Lks. 26 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Paul Moeller

(Signature)

Oct. 6, 1939  
(Date)

Jr. Forester P-1  
(Title)

Corner again.

Give any further facts which will aid in finding this


21 chains distant.

from which this Corner bears N. 47° E.

side of

tree 6 inches diameter, on the

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 146 N. R. 29 W. 5th. Mer.