

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 W Mer.

Section Corner common to Sections

9, 10, 15, and 16

Corner consists of a Not Found (not) in place

State condition ✓

Dimensions above ground ✓ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ✓ is located ✓

✓ Pits are located ✓

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Iron but	marks not	present readable	

Species W. Birch

Diameter 2.4'

Bearing ✓

Distance ✓

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? The Bearing tree is undoubtedly original.

T. A. Johnston


Signature.

Jan 19 '52
Date.

Estimator
Title.

T. 146 R. 29 S. Mer. 113

9-3027 (Make sketch of topography near Corner.)



Metal Location Poster is on a *Norway Pine* tree *12* inches diameter, on the side of *1* from which this Corner bears *1* chains distant. Give any further facts which will aid in finding this Corner again.