

U. S. Department of Agriculture

FOREST SERVICE

E-13  
Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 S. 5th P. Mer.

Section Corner common to Sections

3, 4, 9, and 10

Corner consists of a Round Iron Nail (not) in place

State condition Good and bearing

Dimensions above ground 6 in. x 10 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 146 N
R 29 N
S 9

T 146 N
R 29 N
S 14

--

--

H T
-----

--

--

--

Species Red Pine 1 inch

Diameter 5" 3 1/2"

Bearing S 30° W W

Distance 16' 20 to 30'

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? True corner see notes

on back


Harold K. ...  
(Signature)

Jan. 16, 1932  
(Date)

...  
(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

The corner is in the corner of a lot. The bearing is 100° or about 70° bearing there. One from the corner. My corner with 2 bearings. Any of corner for this.



(Make sketch of topography near Corner)