

Form 574-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

R-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 W 5th Mer.

$\frac{1}{4}$ Corner common to Sections
 _____, _____, 22, and 27

Corner consists of a 2 in. Brass Lapped Pipe (not) in place

State condition Good

Dimensions above ground _____ 8 inches

Sketch grooves, letters, figures, or netches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

$\frac{1}{4}$			
S. 22			
S. 27			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

B.T.	B.T.		

Species Birch Birch

Diameter 6 in 12 in

Bearing N 28° W S. 9 1/2° W

Distance 14 Lks. 39 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Paul Moeller

(Signature)

Oct. 4, 1939

(Date)

Jr. Forester P-1

(Title)

R-15

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

Corner again.

Give any further facts which will aid in finding this

..... chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

		Sec. 27	Sec. 27
		Sec. 22	Sec. 22

(Make sketch of topography near Corner)

T. 14 N. R. 29 W. S. 78 Mer.

K-13 *Post*

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 146 R. 29 Mer.

1/4 Corner common to Sections

22 and 27

Corner consists of a No stake (not) in place

State condition _____

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			<u>22</u>

Species _____ Bass

Diameter _____ 16"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? field notes call for a Balsam

S. Moon

Signature.

Comptroller

Date.

Title.

R-13

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

Tree

tree *16* inches diameter, on the *SOUTH*

Metal Location Poster is on a *Basewood*



(Make sketch of topography near Corner.)

9-3021

T. 146

R. 29

5

R-15 Mer.