

U. S. Department of Agriculture
FOREST SERVICE

P-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 W 5th Mer.

C. 1/4 Corner common to Sections

, 22, and

Corner consists of a Brass Capped Pipe (not) in place
State condition

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

C. 1/4 S. 22			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

Species Birch Maple

Diameter 6 in 8 in

Bearing N 40° W S. 70° E

Distance 26 Lks. 36 Lks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Paul Moller

(Signature)

Jr. Forester P-1

(Title)

Oct. 6, 1939

(Date)

P-15

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

Sec.

Sec.

Sec.

Sec.

22

(Make sketch of topography near Corner)

T. 14 N. R. 29 W. 5 TR. Mer.