

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

P-16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 W 5th Mer.

C.E. $\frac{1}{16}$ Corner common to Sections
 _____, _____, 22, and _____

Corner consists of a Brass capped pipe (not) in place
 State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

C.E. $\frac{1}{16}$			
S 22			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T146N R29W C.E. $\frac{1}{16}$ S 22
--

T146N R29W C.E. $\frac{1}{16}$ S 22
--

--

--

B.T.

B.T.

--

--

Species White Oak Maple

Diameter 12 in 6 in

Bearing N 73° W S 10° W

Distance 51 Lks. 31 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Paul Moeller

(Signature)

Oct. 5, 1939

(Date)

Jr. Forester P-1

(Title)

