

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*Costed*

Chip NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 W S. P. Mer.

Section \_\_\_\_\_ Corner common to Sections  
2, 3, 10, and 11

Corner consists of a Squared post (not) in place  
State condition Sound but weathered

Dimensions above ground 3" X 3" X 24" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 2	—	S 10	S
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

✓ Pits are located ✓

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_


Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? \_\_\_\_\_

*Wm H Pletcher*

Signature.

*Ranger*  
Title.

3/11/29  
Date.



8-3027 (Make sketch of topography near Corner.)

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant.

Corner again.  
 Corner 3 Ch South and 4 Ch West  
 of Station near log stand and in  
 of Spruce Lake through  
 covered by log piles

T. 116 N R. 29 W 5P Mer. E-17