

U. S. Department of Agriculture
FOREST SERVICE

P5/36
#-# J-3

Cypress NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 5th Mer.

SMC Corner common to Sections

....., and 7
Corner consists of a Iron (not) in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 7	S 7		
SMC	SMC		
<i>BT</i>	<i>BT</i>		

Species Oak Oak

Diameter 14" 8"

Bearing N 38 W N 16 E

Distance 45' 36'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Mundy
(Signature)

7/24/35
(Date)

(Title) H-J-3

Corner near shore of lake
from lake
Corner near shore of lake

Corner again.

Give any further facts which will aid in finding this
 character distant:
 from which this Corner bears
 side of *road*
 tree *3* inches diameter, on the *mouth*
 Metal Location Poster is on a *sh*

<p>Sec.</p>	<p>Sec.</p> <p><i>Corner lake</i></p>
<p>Sec.</p>	<p>Sec.</p> <p><i>Point</i></p> <p>7</p>

(Make sketch of topography near Corner)

T. 1st 6 R. 30 Mer. *52*