

U. S. Department of Agriculture  
FOREST SERVICE

J-9

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 146N R. 30W 5th Mer.

Sec. Corner common to Sections  
8, 9, 16, and 17

Corner consists of a Bronze Cap in cement (not) in place

State condition Good  
Also Iron Stake 30" (6" inches  
Dimensions above ground

Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

			<u>46</u>
<u>5</u>	<u>5</u>	<u>5</u>	<u>1730</u>
<u>8</u>	<u>17</u>	<u>16</u>	<u>59</u>
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species None

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? \_\_\_\_\_

H.C. Norman  
(Signature)

4/20/37  
(Date)

J-9

Give any further facts which will aid in finding this  
 Corner again.  
 from which this Corner bears  
 chains distant  
 Metal Location Pester is on a  
 tree inches diameter, on the  
 side of



(Make sketch of topography near Corner)

T. 144 N. R. 30 W. 57th Mer. J-9