

U. S. Department of Agriculture
FOREST SERVICE

6-9

C. B. P. P. S. W. A. NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 Mer.

Quarter (1/4) Corner common to Sections 8 and 9

Corner consists of a S. L. O. (not) in place



State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch J.P.

Diameter 8" 6"

Bearing E NW

Distance 70' 50'

Do you believe this to be a genuine Land Office Corner?

If not, why?

M. J. Murphy
(Signature)

12/5/34
(Date)

(Title)

6-9

