

U. S. Department of Agriculture
FOREST SERVICE

J-11

Chipp

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 Mer. 5

1/4 Corner common to Sections 9, and 16


Corner consists of a Brass top (not) in place
State condition Good

Dimensions above ground 1.0 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam

Diameter 5.5

Bearing 355°W N17°W

Distance 0.875 0.400

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

(Date)


(Title)

J-11

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)