

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

E-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *146* R. *30* *5th* Mer.

1/4 ~~*1/4*~~ Corner common to Sections
 _____, _____, *4*, and *9*

Corner consists of a *1/4* (not) in place

State condition *ungrounded*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4</i>			
<i>BQ</i>			

Species *Aspen*

Diameter *12"*

Bearing *NW*

Distance *60'*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

[Signature]
 (Signature)


12/5/34
 (Date)

(Title)

E-11

Corner again.
Abundant clear rock and
H. Chas. mouth of Canon

Metal Location Poster is on a *Canon*
tree 12 inches diameter, on the *mouth*
side of *mouth* from which this Corner bears *N 20 W*
60 chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. J. G. R. 50 Mer. E-11