

U. S. Department of Agriculture  
FOREST SERVICE

Posted P-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 30W 5th Mer.

Quarter Corner common to Sections

21, and 22

Corner consists of a Brass Caped pipe (not) in place


State condition Good

Dimensions above ground 9" under Surface of Road inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4  
5  
21

1/4  
5  
22

BT

BT

Species N. Pine N. Pine

Diameter 14" 12"

Bearing N32°5'W N. 69°E

Distance 82 3/4 8'

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? \_\_\_\_\_

J. A. Gzelhaug

(Signature)

10/23/34

(Date)

Tech. Eng.


(Title)

P-13

Faded text on ruled lines, possibly bleed-through from the reverse side of the page.

Corner again:

Give any further facts which will aid in finding this  
..... chains distant  
from which this Corner bears  
side of  
tree ..... inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 196N. R. 30W. S. 44. Mer. P-13