

U. S. Department of Agriculture  
FOREST SERVICE

L-14

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 Mer.

W.C. 1/4 Corner common to Sections

15, and

Corner consists of a N.P.O. (not) in place

State condition Good

Dimensions above ground 10" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W 1/4
S-15

W 1/4
S-15

--

--

BT
----

BT
----

--

--

Species Tam Tam

Diameter 6" 7"

Bearing S-10°E E 40°N

Distance 32 ch 17 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

4/25/35  
(Date)


(Signature) [Handwritten Signature]  
(Title)

L-14

.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....

*E + M*  
*Corner again*

Metal Location Poster is on a tree ..... inches diameter, on the side of ..... from which this Corner bears ..... chains distant.  
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

L-14

95/36

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 Mer.

W.C. or P. 9 1/4 Corner common to Sections  
-----, -----, and 15

Corner consists of a Y.L.O. Cup (not) in place  
State condition Good

Dimensions above ground ----- 10 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W 1/6
S-45

W 1/6
S-15



BT
----

BT
----

--

--

Species Tam Tam

Diameter 6" 7"

Bearing S 10° E N 40° E

Distance .32 ch .17 ch

Do you believe this to be a genuine Land Office Corner? ye

If not, why? -----

[Signature]  
(Signature)


4/25/35  
(Date)

(Title) L-14

*[Faint, mostly illegible text on a ruled background]*

Corner again.

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Ac Ac 76 Sec. 18 

(Make sketch of topography near Corner)

Mer. T. 1st R. 50 L-14