

U. S. Department of Agriculture  
FOREST SERVICE

G-15

Chipman NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 Mer.

Center 1/4 Corner common to Sections

10, and

Corner consists of a Pipe & Cap (~~rod~~) in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>C 1/4 C</u> <u>310</u>
------------------------------

<u>C 1/4 E</u> <u>310</u>
------------------------------

--

--

<u>BT</u>
-----------

<u>BT</u>
-----------

--

--

Species NORWAY Norway

Diameter 12 in 14 in

Bearing NW W

Distance .730 2.300

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Reneith Wray  
(Signature)

4, 23, 35  
(Date)


(Title)

G-15

-----  
-----  
-----  
-----  
-----  
-----  
-----  
-----  
-----  
-----

Corner again.

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 146 R. 30  
6-15  
Mior.