

U. S. Department of Agriculture
 FOREST SERVICE

A-15

 Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 Mer.

 Corner common to Sections
 3, $4\frac{1}{4}$, and 34

 Corner consists of a _____ (not) in place
 State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

 Sketch markings of Bearing Trees (or Rocks) in proper box and
 fill blanks below, giving bearings from Corner to Trees and
 Distances in Links.

$\frac{1}{4}$ C
BT

$\frac{1}{4}$ C
BT

NW

NE

--

--

Species *Jack Pine* *Jack Pine*Diameter *7 in* *7 in*Bearing *S E* *S W*Distance *.90* *.66*Do you believe this to be a genuine Land Office Corner?

If not, why? _____

1-A

UNITED STATES FOREST SERVICE

Grand-Entré Twp

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

S.W.

side of

tree 5 inches diameter, on the S.W.

Metal Location Poster is on a Jack Pine

