

U. S. Department of Agriculture
FOREST SERVICE

Posted
T-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 30W 5th Mer.

Quarter Corner common to Sections
26, and 27

Corner consists of a Brass Coped Pipe (not) in place
State condition Good

Dimensions above ground 8 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/45 27

1/45 26

--

--

BT.

BT.

--

--

Species J. Pine J. Pine

Diameter 10" 8"

Bearing N. 49° 45' W. N. 80° 15' E.

Distance 239 253

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____


J. P. Gjolhaug
(Signature)

9/26/39
(Date)

Tech. Eng.
(Title)

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 196N. R. 30W. 57 Mer. T-17