

U. S. Department of Agriculture  
FOREST SERVICE

A-17

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146-147 R. 30 Mer.

Section Corner common to Sections  
2, 3, 34, and 35

Corner consists of a pipe + wooden stake (not) in place  
State condition Solid

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S	S	S	S
34	3	2	35

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

No	B.T.'S	

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

(Signature)

(Date)


(Title)

A-17

A-17

Corner again.  
 James Cunningham W & J  
 with view to how  
 cut out.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of *Corner*  
 tree 11 inches diameter, on the *SW*  
 Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

A-17

R

T