

U. S. Department of Agriculture
FOREST SERVICE

T-18


Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W 5th Mer.
9 1/4 Corner common to Sections

-----, -----, -----, and 26-----
Corner consists of a metal cap (not) in place
State condition good

Dimensions above ground 4 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>CW 1/16</u>	
<u>S. 26</u>	

<u>CW 1/16</u>	
<u>S. 26</u>	

<u>B.T.</u>	
-------------	--

<u>BT</u>	
-----------	--

Species J. P. J. P.

Diameter 11" 14"

Bearing S. 73 E N 82 E

Distance 48 lks 76 lks

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

Harold Honnas

(Signature)

Jan. 15, 1937

(Date)

(Title)

T-18

21-7

SECTION 26

COMPLETED BY

Corner again.

Give any further facts which will aid in finding this

chain distant.


S 73 E

from which this Corner bears

side of tree

tree 11 inches diameter, on the North

Metal Location Poster is on a



(Gives sketch of topography near Corner)

T-18