

U. S. Department of Agriculture  
FOREST SERVICE

*P*  
*N-18*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *146* R. *30* *5th* Mer.

*N 1/4* Corner common to Sections  
*14*, and *23*

Corner consists of a *4 20* (net) in place  
State condition *Good*

Dimensions above ground *8* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>W 1/6</i>	<i>W 1/6</i>		
<i>S-14</i>	<i>S-23</i>		
<i>BT</i>	<i>BT</i>		

Species *Asb* *W. Oak*

Diameter *4"* *1 1/2"*

Bearing *NE* *S 40 E*

Distance *25 ch* *40 ch*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*J. Murphy*  
(Signature)

*5/11/35*  
(Date)

(Title) *N-18*

Department of Agriculture

NATIONAL FOREST

COMMISSION OF THE PUBLIC SURVEY

UNITED STATES DEPARTMENT OF AGRICULTURE

Corner again.

Give any further facts which will aid in finding this

of chains distant.


from which this Corner bears

side of

tree 14 inches diameter, on the

Metal Location Poster is on a

NW 1/4 23 14



(Make sketch of topography near Corner)

N-18

Mer.

5 1/2

30

R

1 1/2

T

U. S. Department of Agriculture  
FOREST SERVICE

N-18

----- NATIONAL FOREST  
**CORNERS OF THE PUBLIC SURVEY**

T. 14 R. 4 Mer.

W-44 Corner common to Sections  
14, 15, and 23

Corner consists of a stone (not) in place  
State condition good

Dimensions above ground 7 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of stone is located at corner

Pits are located at corner

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>W-44</u>
<u>5-14</u>

<u>W-44</u>
<u>5-14</u>



<u>BT</u>
-----------

--

--

--

Species Ash W-44

Diameter 4" 4"

Bearing NE S 45° E

Distance 25.5 11.5

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? None

5/14/35  
(Date)

(Signature) J. S. Samples  
(Title)

N-18

.....

.....

.....

.....

.....

.....

.....


.....

.....

.....

Corner again.

Give any further facts which will aid in finding this  
 ..... chains distant.  
 from which this Corner bears .....  
 side of .....  
 tree ..... inches diameter, on the  
 Metal Location Poster is on a *As 5*



(Make sketch of topography near Corner)