

U. S. Department of Agriculture
FOREST SERVICE

U-19

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 30 W 5th Mer.

13 1/6 Corner common to Sections
26, _____, _____, and _____

Corner consists of a metal cap (not) in place

State condition good

Dimensions above ground 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

26	26	26	26

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

CS 1/16
S. 26

CS 1/16
S. 26

B.T.

B.T.

Species J. P. J. P.

Diameter 8" 7"

Bearing S 47 W N 19.5 W

Distance 54 lks 47 lks

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Harold Hennes
(Signature)

Jan. 14, 1937
(Date)

(Title)

U-19

U-19

U.S. DEPARTMENT OF AGRICULTURE

U.S. DEPARTMENT OF AGRICULTURE

U.S. DEPARTMENT OF AGRICULTURE

U.S. DEPARTMENT OF AGRICULTURE

U.S. DEPARTMENT OF AGRICULTURE

U.S. DEPARTMENT OF AGRICULTURE

U.S. DEPARTMENT OF AGRICULTURE

Corner again.

Give any further facts which will aid in finding this

54 chains distant.


from which this Corner bears

S 47 W

side of Tree

tree 8 inches diameter, on the North East

Metal Location Poster is on a Jack Pine



(Make sketch of topography near Corner)

U-19