

U. S. Department of Agriculture
FOREST SERVICE

T-20

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 30 5th Mer.

8 1/16 Corner common to Sections
_____, _____, and 26

Corner consists of a metal cap (net) in place

State condition good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

26	26	26	26

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

CB <u>1/16</u>	
<u>8.26</u>	

CB <u>1/16</u>	
<u>8.26</u>	

B.T.	
------	--

B.T.	
------	--

Species J.P. J.P.

Diameter 4.5" 6"

Bearing N62E S19W

Distance 44 lks 9 lks

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Harold Hommes
(Signature)

Jan. 12, 1937

(Date)

(Title)

T-20

CORNERS OF THE PUBLIC SURVEY

Road 1.7 chains east o corner

Corner again.

Give any further facts which will aid in finding this


tree. Give distance

from which this corner bears

side of trees

tree 5 inches diameter, on the North

Metal Location Poster is on a Jack Pine



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

T-20, 20
T-20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 30 5th Mer.
8 1/16

Corner common to Sections
and 26

Corner consists of a metal cap (not) in place
State condition good

Dimensions above ground 3 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

26	26	26	26
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

CE 1/16
S.26

CE 1/16
S.26

B.T.

B.T.

Species J.P.
Diameter 4.5"
Bearing N62E
Distance 44lks

J.P.
5"
S19W
9 lks

Do you believe this to be a genuine Land Office Corner? YES
If not, why?

Harold Hermes
(Signature)

Jan. 12, 1937
(Date)

(Title)

T-20

April 1, 1954

Corner of East 1st and Main

Corner again.

Give any further facts which will aid in finding this


tree. Give distant

from which this corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Map of topography near Corner)

T. J. R. Mer. 1-20