

U. S. Department of Agriculture
FOREST SERVICE

DE-5
D-E-5

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 146N R. 30W S. 5 Mer.

MC Corner common to Sections

6, and 5

Corner consists of a Brass Cap on Pipe in place



State condition Good

Dimensions above ground 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch

Diameter 6"

Bearing Due west

Distance 37 lk.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

H C Norman
(Signature)

4/20/37
(Date)

D-E-5

On point or bank
into Kitchi Lake

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

D-E-5

T. 146 N R. 30 W

Mer.