

U. S. Department of Agriculture
FOREST SERVICE

E-F-5

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEYT. 196 N. R. 30 W. 5th Mer.
M. C. Corner common to Sections_____, _____, 7, and 8
Corner consists of a Bross Sept pipe (not) in place
State condition GoodDimensions above ground 8 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

T. 196 N. R. 30 W. Sec. 7 M. C.			
B. T.			

Species W. Oak _____Diameter 6 in _____Bearing N. 1° W. _____Distance 23 1/2 _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

9/20/37 _____

(Date)

A C Norman
(Signature)

E-F-5

