

U. S. Department of Agriculture
FOREST SERVICE

EF-7 3/2

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *146* R. *30* *5th* Mer.

Boundary Line Corner common to Sections
....., and *8*

Corner consists of a *4 1/2 Cap* (not) in place
State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>Description on Cap</i>							
	<i>AP 4</i>						
	<i>API</i>						
	<i>TR 187</i>	<i>TR 186</i>					
N	W	S	E	NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>No</i>	<i>Bts</i>		

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

Murphy
(Signature)

9/17/35
(Date)

(Title) *E-F-7*

Handwritten notes on a ruled page, including the number '21' and some illegible text.

Corner again.

Give any further facts which will aid in finding this

of chains distant.

from which this Corner bears

16.10

side of

corner

tree 16 inches diameter, on the

16.10

Metal Location Poster is on a

Board

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

E-F-7

T. H. R. 30 Mer.