

Copied
Posted
5/26
F1

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 31-32 5th Mer.

N 1/2 Corner common to Sections
7-146-31- and 12-146-32


Corner consists of a *Y 50* (not) in place
State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N

W

S

E

NW

SW

SE

NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 146
R-32
S-12

T 146
R-31
S-7

[Blank box]

[Blank box]

BT

BT

[Blank box]

[Blank box]

Species *Maple Elm*

Diameter *4" 5"*

Bearing *N 80W S 53 E*

Distance *71ch 11ch*

Do you believe this to be a genuine Land Office Corner *Yes*

If not, why? _____

Murphy
(Signature)

4/19/35
(Date)

(Title)

F-1

Corner again.

Give any further facts which will aid in finding this

~~of~~ chains distant.

from which this Corner bears

SBSM

side of *main*

tree 8 inches diameter, on the

521

Metal Location Poster is on a

Poster

	Sec.		Sec.
	Sec.		Sec.
	7		12
	146-31		146-32

(Make sketch of topography near Corner)

T. 146 R. 31-32
Met. *521* *522* *523*
F-1

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

F-1
 F1

NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 146. R. 31-32 Mer.

N 1/4 Corner common to Sections

7, and 12

Corner consists of a Iron Cap (not) in place

State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

N 1/4		N 1/4	
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T146
 R-32
 S-12

T146
 R-31
 S-7

BT

BT

Species Maple Elm

Diameter 4" 8"

Bearing W 110' N E 87' S

Distance 3 1/2 ch 1 1/2 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

M. F. Murphy
 (Signature)

4/10/35
 (Date)

(Title) F 1/4-1

U.S. FOREST SERVICE

CORNERS OF THE PUBLIC SURVEY

Handwritten: Section 12, Township 2 N, Range 3 W, T12N R3W
Handwritten: Section 7, Township 2 N, Range 3 W, T12N R3W

Give any further facts which will aid in finding this


Handwritten: chains distant

from which this Corner bears *Handwritten:* W 56.5

side of *Handwritten:* N 1/4 Sec 7

tree *Handwritten:* 8 inches diameter, on the S W

Metal Location Poster is on a *Handwritten:* 1/2 Sec 7



(Make sketch of topography near Corner)