

U. S. Department of Agriculture  
FOREST SERVICE

E-2 E-2

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 31 Mer.

W 1/4 Corner common to Sections

6, and 7

Corner consists of a N.S.P. Cap (not) in place



State condition Good

Dimensions above ground 15" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T146  
R 31  
5-6

T146  
R 31  
5-7

BT

BT

Species Aspen ASPER

Diameter 12" 10"

Bearing N 39' W S 27' W

Distance 64 ch 37 ch

Do you believe this to be a genuine Land Office Corner? Y

If not, why? \_\_\_\_\_

M. B. Gandy  
(Signature)

4/10/35  
(Date)

E-2 E-2

COMMENTS ON CORNER


Corner again.  
Give any further facts which will aid in finding this

chain distant.

from which this Corner bears 529.5

side of *see from* tree 10 inches diameter, on the *see*

Metal Location Poster is on *see*



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

P 5/22  
E-2 E2

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *12/6* R. *31* *52h* Mer.

*W 7/6* Corner common to Sections

-----, -----, *6*, and *7*  
Corner consists of a *S 20* (not) in place

State condition *Good*

Dimensions above ground ----- *15* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

*T 146*  
*R-31*  
*S-6*

*T 146*  
*R-31*  
*S-7*

--

--

*BT*

*BT*

--

--

Species *ASPEN ASPEN*

Diameter *12" 10"*

Bearing *N39W S27W*

Distance *26.1ch 37ch*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? -----

*Murphy*  
(Signature)

*4/10/33*  
(Date)

(Title)

Blank lined area at the top of the page.

*Corner on north side*  
*of small post hole*

Corner again.

Give any further facts which will aid in finding this

57 chains distant.

from which this Corner bears

S 29 E

side of


*North line*

tree 10 inches diameter, on the

*North*

Metal Location Poster is on a

*Post*



(Make sketch of topography near Corner)

T. 146 R. 31  
S. 22. N. 01  
4-2