

U. S. Department of Agriculture
FOREST SERVICE

C7
posted
C-7

Chippewa Trail
NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 31 W S Mer.

C 1/4 S 5

Corner common to Sections

5



Corner consists of a *bronz exp.* (not) in place
State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Norway P.*

White P.

Diameter *W*

6"

Bearing *W*

NE

Distance *2.5 ch.*

1 ch.

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why?

S. Randall
(Signature)

Feb 16, 1934
(Date)

Confession
(Title)

C-7

C-7

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

Corner again.
Give any further facts which will aid in finding this
chain distant

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears

