

U. S. Department of Agriculture  
FOREST SERVICE

V-16

V-16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 31 5<sup>th</sup> Mer.

East 1/16 Corner common to Sections  
27, and 34

Corner consists of a Brass capped pipe (not) in place

State condition

good

Dimensions above ground 8 inches

Sketch grooves, lumps, knobs, or notches, on proper face or edge.

CARDINAL POSITION                          DIAGONAL POSITION

N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.

E 16  
S 34

E 16  
S 27

B. T.

B. T.

Species N. P. R. Oak.

Diameter 12"

Bearing S. 39° 45' W. N. 22° E. W.

Distance 18 29

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl S. Headland

3/19/35  
(Date)

J. F. Eng.  
(Signature)

N-18

