

Form 972-3- Revised May, 1931
 U. S. Department of Agriculture
 FOREST SERVICE

C-17

NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 146 R. 31 Mer.
222 Corner common to Sections
2, and _____

Corner consists of a N.S.O. (no) in place
 State condition Good

Dimensions above ground 4 1/2 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.
 CARDINAL POSITION DIAGONAL POSITION

N	W	S	E	NW	SW	SE	NE

Material of wood is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper position
 fill blanks below, giving bearings from Corner to Tree and
 Distances in Links.

<u>146-31</u> <u>S-2</u>	<u>146-31</u> <u>S-2</u>		
<u>BT</u>	<u>BT</u>		

Species W. Oak R. Oak
 Diameter 7
 Bearing N 8° W S 3° W
 Distance 58 chs 55 chs

Do you believe this to be a genuine Land Office Corner?
 If not, why?

[Handwritten signature]

UNITED STATES DEPARTMENT OF AGRICULTURE

1-3

CORNERS OF THE PUBLIC SUBWAY

Give any further facts which will aid in finding this
chain distant
from which this Corner bears
inches diameter, on the
side of

Give any further facts which will aid in finding this
chain distant
from which this Corner bears
inches diameter, on the
side of

<p>See</p>	<p>See</p>	<p>See</p>	<p>See</p>
<p>See</p>	<p>See</p>	<p>See</p>	<p>See</p>

U. S. Department of Agriculture
FOREST SERVICE

257/36
G19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 31 5th Mer.

C 14 Corner common to Sections _____, _____, and _____


Corner consists of a 4 1/2 (not) in place
State condition Good

Dimensions above ground _____ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T146
R-31
Sec 2

T146
R-31
S 2

BT

BT

Species NOAK ROCK

Diameter 7" 9"

Bearing N5W S5W

Distance 38ch 58ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. M. [Signature]
(Signature)

4/9/35
(Date)

(Title)

G19

Corner again.

Give any further facts which will aid in finding the


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

C-19

100

100

100

100

T. 1176 R. 31