

U. S. Department of Agriculture  
FOREST SERVICE

2-21 2-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 & 146 R. 31 5<sup>th</sup> Mer.

Sec. Corner common to Sections  
35, 36, 37, and 38



Corner consists of a Dress in concrete (not) in place  
State condition good

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N

W

S

E

NW

SW

SE

NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 146 N.  
R. 31 W.  
S. 36

T. 145 N.  
R. 31 W.  
S. 1

T. 145 N.  
R. 31 W.  
S. 2

T. 146 N.  
R. 31 W.  
S. 35

B. T.

B. T.

B. T.

B. T.

Species W. Oak W. Oak W. Oak W. Oak

Diameter 7" 7" 6" 12"

Bearing N. 37 1/2 E S 56 E S 49 1/2 W N. 69 W

Distance 62 lks 53 lks 4 1/2 lks 17 1/2 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Carl Steadland

3/19/35  
(Date)

E 79  
(Title)

S. 51  
2-21

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ... R. ...

Corner common to ...

... and ...

Corner consists of a ... in place

Corner ...

Give any further facts which will aid in finding this

Dimensions above ...

Station ...

Diagonal ...

Cardinal position ...

From which this corner bears

Side of ...

Tree inches diameter, on the

Special location corner is on a

N E W S W N E

... located

... located

... located

... located

... located

... located

... located

... located

... located

... located

... located

... located

... located