

U. S. Department of Agriculture

FOREST SERVICE

G-23

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 31 Mer.

Corner common to Section 4

Corner consists of a 12' and 2' 50" (not) in place



State condition

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Oak R. 506

Diameter 7 1/2 8

Bearing W. 10 S N. 10 E

Distance 9 25

Do you believe this to be a genuine Land Office Corner?

If not, why?

Blank space for handwritten notes.

Date 4/15/35 (Date) B (Title)

G-23

Section 2

6-53


CORNERS OF THE PUBLIC SURVEY

Section 2

about 4 chains
Small hole to the west

Give any further facts which will aid in finding this
bearing distant.

from which this Corner bears
side of
inches diameter, on the
Metal Location Poster is on a



(State sketch of topography near Corner)

6-23

6-23