

Rangers copy

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY



T. 147 N., R. 25 W., 5th Mer.
SE 1/16 Corner common to Section #
7, , and

Corner consists of a cedar post (not) in place
State condition good

Dimensions above ground 30 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 #7 S	Indistinguishable		
BT	BT		

Species maple ash
 Diameter 12" 14"
 Bearing N32°W S14°W
 Distance 49 links 45 links

Do you believe this to be a genuine Land Office Corner? No
 If not, why? Corner set by Knoblauch. B.T.'s scribed by county surveyor.


C. J. Knoblauch
(Signature)

asst. Ranger
(Title)

12/1/36
(Date)

Corner again.
 Give any further facts which will aid in finding this
 corner again.
 Snow was on ground and county corner
 could not be located so we set标杆
 post, painted white, whose position of
 and described on B.T.'s indicated corner
 should be.
 Search when ground is bare may
 reveal county corner near white soda
 post.

Metal Location Posters on the two bearing
 tree 5 inches diameter, on the described on other
 side of page. They face the corner.
 from which this Corner bears
 chains distant.



(Make sketch of topography near Corner)

T. 147 N., R. 25 W., 5th Mer.