

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

N-11

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 25 Mer.

1/4 Corner common to Sections
16-21, and

Corner consists of a 50. post (not) in place
State condition poor - rotted off

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Cedar Birch 5706

Diameter 10" 8"

Bearing N10W 385W

Distance 33' 26'

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

R. H. Cherry
(Signature)

D. S. R.
(Title)

8-18-55
(Date)

Corner again.

Give any further facts which will aid in finding this

_____ chains distant.


_____ from which this Corner bears
True
of bearing

side of

tree *4* inches diameter, on the

500th
Aspen

Metal Location Poster is on a



(Make sketch of topography near Corner)