

U. S. Department of Agriculture

FOREST SERVICE

marked G21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 25 Mer. 5

1/4 Corner common to Sections 12, _____, _____, and _____



Corner consists of a _____ (not) in place State condition _____

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species	<u>N. P. Spruce</u>	<u>200</u>	<u>300</u>
Diameter	<u>14"</u>	<u>14"</u>	<u>14"</u>
Bearing	<u>N. W.</u>	<u>S. E.</u>	<u>S. E.</u>
Distance	<u>1/2</u>	<u>1/2</u>	<u>1/2</u>

Do you believe this to be a genuine Land Office Corner? yes
If not, why? _____


(Signature)

1/21/22
(Date)

(Title)

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 25 Mer.

State of N. Dak.