

U. S. Department of Agriculture
FOREST SERVICE

P-25

~~CHIPPWA~~

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147E R. 37 Mer. 5

Corner common to Sections _____, _____, _____, and _____

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N. W. S. E.



--	--	--	--

NW. SW. SE. NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Tree (Dead)

Diameter 7"

Bearing S52W

Distance 0.10

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Larsen

(Signature)

4-1-35

(Date)

Geo. Marshall

(Title)

U. S. Department of Agriculture
FOREST SERVICE

*ALREADY
POSTED
Q25*

CHIPPEWA

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 25W 5 Mer.

0 11 4 1/2 P.M.

Corner common to Sections

24

Corner consists of a _____ (not) in place



State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tan (Dead)

Diameter 7"

Bearing S52W

Distance 0.10

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Larson

(Signature)

GCC Enrollee

(Title)

4-1-35

(Date)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.10

from which this Corner bears

8527

Tree


side of

tree 7" inches diameter, on the

85

Metal Location Poster is on a

Tree (85)



(Make sketch of topography near Corner)

T. 1147N R. 25W Mer. 5

U. S. Department of Agriculture
FOREST SERVICE

P-25

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147N R. 25W 5 Mer.

1/4 Corner common to Sections
23, and 24

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>			
<u>524</u>			
<u>BT</u>			

Species Lam (Dead)

Diameter 7"

Bearing S52W

Distance 0.10

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Larson
(Signature)

4-1-35
(Date)

C.C.C. Enrollee
(Title)

.....
.....
.....
.....
.....
.....
.....
.....

Corner again.

Give any further facts which will aid in finding this


0.10 chains distant.

From which this Corner bears 552 W

side of tree

tree 7 inches diameter, on the SW

Metal Location Poster is on a Tom (BT)



(Make sketch of topography near Corner)

T. 197N R. 25W Mer. 5