

U. S. Department of Agriculture  
FOREST SERVICE

U1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.

1/4 Corner common to Sections  
25, and 30.

Corner consists of a Iron Pipe (not) in place


State condition New.

Dimensions above ground 2" - 27" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. OAK W. OAK

Diameter 7" 6"

Bearing S. 52° E S. 57° W

Distance .55 1.13

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Balke

(Signature)

Leader

(Title)

1937

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 R. 26 Mer.

5-25