

U. S. Department of Agriculture  
FOREST SERVICE

*Posted*  
*P1*

*Chippewa* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. *147 N* R. *26 W-27 W* S+4 *Prin Mer.*

*Quarter* Corner common to Sections

*19*, and *24*

Corner consists of a *post* (not) in place


State condition

Dimensions above ground *4* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *B. Spence*

Diameter *1.5"*

Bearing *N.W.*

Distance *12.1 Ks.*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why?

*Only a part of the inscription remains on this one witness tree.*

*Carroll W. Carlson*

(Signature)

*3-22-34*


(Date)

*Leah Foreman*

(Title)

There is an old blazed line to the north, we are to observe about 20 ft. The section corner marking on the section corner is to the west of the section corner. The distance to the section corner is to the west and 20 ft. by chaining.

Corner again.  
 Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree..... inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147N R. 26W - 27W 5th Prin. Mer.