

U. S. Department of Agriculture
FOREST SERVICE

N-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.

Sec. Corner common to Sections

13, 18, 19, and 24

Corner consists of a Concrete Monument (not) in place

State condition Just Erected

Dimensions above ground 6" — 20 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>R27</u>	<u>S-18</u>
<u>S-13</u>	
<u>S24</u>	<u>S19</u>
N	W
S	E

<u>Marked</u>			
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>T-147N</u>	<u>T-147</u>	<u>T-147N</u>	<u>T-147N</u>
<u>R27W</u>	<u>R27W</u>	<u>R27</u>	<u>R^o</u>
<u>S-18</u>	<u>S-13</u>	<u>S24</u>	
<u>B.T.</u>	<u>B.T.</u>	<u>B.T.</u>	

Species Norway Spr. N.P. Cedar

Diameter 12" 15" 6"

Bearing N 77° E N 52° W S-49° W

Distance .39 .79 .34

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Balk
(Signature)

1936
(Date)

Leader
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

2-11-18

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 Mer.

Sec. Corner common to Sections
 13, 14, 19, and 24

Corner consists of a ~~concrete marker~~ ^{metal} (not) in place

State condition new

Dimensions above ground 6" x 20" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

R-27	R-26
S-13	S-18
S-24	S-19
N	W
S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 147 R. 26 S. 19	T. 147 R. 27 S. 13	T. 147 R. 27 S. 24	
B. T.	B. T.	B. T.	

Species N.P. N.P. Cedar
 Diameter 12" 15" 5"
 Bearing N. 77° E N. 52° W S. 49° W
 Distance 39 179 34

Do you believe this to be a genuine Land Office Corner? Yes.


If not, why? _____

B. alke.
 (Signature)

1936
 (Date)

Leader
 (Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 N. R. 26 W. Mer.

U. S. Department of Agriculture
FOREST SERVICE

N-1-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *147* R. *26* Mer.

Sec. _____ Corner common to Sections

13, *14*, *19*, and *24*

Corner consists of a *Concrete monument* (not) in place

State condition *new*

Dimensions above ground *6" x 20"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>R-27</i>	<i>R-26</i>
<i>S-13</i>	<i>S-18</i>
<i>S-24</i>	<i>S-19</i>
N	W S E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>T. 147</i>
<i>R. 26</i>
<i>S-18</i>

<i>T. 147</i>
<i>R. 27</i>
<i>S-13</i>

<i>T. 147</i>
<i>R. 27</i>
<i>S-24</i>

--

<i>B. T.</i>

<i>B. T.</i>

<i>B. T.</i>

--

Species *N.P.* *N.P.* *Cedar*

Diameter *12"* *15"* *5"*

Bearing *N. 77° E* *N. 52° W* *S. 49° W*

Distance *39* *79* *34*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

B. Baker


(Signature)

1936
(Date)

Leader
(Title)

(Make sketch of topography near Corner)

T. 147 R. 26 S. 5. Mer.



Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

U. S. Department of Agriculture

FOREST SERVICE

N 1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 Mer.

Sec.

Corner common to Sections

13, 18, 19, and 24

Corner consists of a concrete monument (net) in place

State condition New

Dimensions above ground 6 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

R-27	S-30
S-13	S-14
S-24	S-19

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T-147
N.P.
S-19

T-147
S-27
S-3

T-147
R-27
S-24

R-27

S-

R-27

--

Species N.P. N.P. Cedar

Diameter 12" 15" 5"

Bearing N-77°E N-10°45' S-17°30'

Distance 37 17 34

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why?

Bulke

(Signature)

1936

(Date)

Cooper

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)