

U. S. Department of Agriculture
FOREST SERVICE

El

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 26W 5th Mer.

Section Corner common to Sections
1, 12, 6, and 7

Corner consists of a woodpost (not) in place

State condition good

Dimensions above ground 4" x 4" x 20" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S 7147N R26W	5 12	5 7	5 6
--------------------	---------	--------	--------

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S
7147N
R26W



B.T.



Species ASPEN

Diameter 12"

Bearing N26W

Distance 43

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Walter K. ...

(Signature)

Leader

(Title)


10/10/38

(Date)

Corner again. *off top of road near N.S. 17.5 of cor.*

Give any further facts which will aid in finding this side of from which this Corner bears chains distant.

Metal Location Poster is on *the B.T.* inches diameter, on the



(Make sketch of topography near Corner)

T. 146 N R. 26 W 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

E1

11777 NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 17 R. 26 5th Mer.

Corner common to Sections 11, 12, 13, and 14

Corner consists of a stone (set) in place

State condition new

Dimensions above ground 6x24" - 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

11777			
11777		26	5
11777	11777	11777	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

11777
11777
11777

11777
11777
11777

11777
11777
11777

11777
11777
11777

11777

11777

11777

11777

Species 11777 11777 11777 11777

Diameter 10" 10" 10" 10"

Bearing 11777 11777 11777 11777

Distance 15' 15' 15' 15'

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Signature) 11777

(Date) 11777

(Title) 11777

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 1917 R. Mer.

U. S. Department of Agriculture
FOREST SERVICE

151

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.

Sec.

Corner common to Sections

1, 12, 6, and 7

Corner consists of BRASS CAP IN CEMENT (set) in place

State condition NEW

Dimensions above ground 6" x 24" - 20" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

T. 147			
R. 27	S. 1	S. 6	R. 26
T. 146	S. 12	S. 7	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 147 R. 26 S. 7	T. 147 R. 27 S. 12	T. 147 R. 27 S. 6	T. 147 R. 26 S. 1
B. T.	B. T.	B. T.	B. T.

Species	d. P.	d. P.	d. P.	d. P.
Diameter	16"	14"	10"	12"
Bearing	S. 75° E	S. 27° W	N. 33° E	N. 47° W
Distance	.52	.40	.24	.24

Do you believe this to be a genuine Land Office Corner? Yes.
If not, why? _____

Balke


(Signature)

Leader

(Title)

1937
(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 26 S. 24 Mer.