

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

C 1

NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 47 R. 25-26 Mer.

Corner common to Sections  
4, 1, and 6

Corner consists of a 2" Pipe Brass (not) in place  
 State condition Good

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 147 R 26 S 1	T 147 R 26 S 1	T 147 R 25 S 6	
BT	BT	BT	

Species White Brass Iron

Diameter 5" 6" 4"

Bearing N 23 W S 64 W N 40 E

Distance 21' 11.3' 11.3'

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_


Joseph F. Lausche  
 (Signature)

10-29-56  
 (Date)

Eng. Aid  
 (Title)

Corner again.  
 Brass cap cor is on cor  
 of old fence line  
 tag on post along Rd 2188  
 fence line runs north to cor  
 from N.D.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 N 64 E  
 side of  
 tree 6 inches diameter, on the  
 N E  
 Metal Location Poster is on a  
 Brass wood



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 31 S. 46 Mer.

Corner common to Sections

14, 15, and 16

Corner consists of a stone (not) in place



State condition new

Dimensions above ground 2 1/2" x 2 1/2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species oak oak

Diameter 6" 6"

Bearing N. 70° E S. 20° W

Distance 34 16

Do you believe this to be a genuine Land Office Corner? yes


If not, why? \_\_\_\_\_

(Signature)

1937 (Date)

(Title)

Metal Location Poster is on a  
 tree inches diameter, on the  
 side of  
 from which this Corner bears  
 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near Corner)

T. R. Mer.